1426-1446 East Baltimore Street (Commerical Buildings) 1442 East Baltimore Street Baltimore (Independent City) Maryland

HABS No. MD-904-H

HABS MD, 4-BALT, 153 H-

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION, NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

Form (0-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS MD, 4-BALT, 153 H-

ARCHITECTURAL DATA FORM

TATE	COUNTY		TOWN OR VICINITY	
Maryland			Baltimore	
HISTORIC NAME OF STRUCTURE (INCLUDE SDURCE FOR NAME) HABS NO.				
1426-4Œast Baltimore Street (Commercial Buildings) MD-904-H SECONDARY OR COMMON NAMES OF STRUCTURE 1442 East Baltimore Street				
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)				
1442 East Baltimore Street				
DATE OF CONSTRUCTION (INCLUDE SOURCE) ARCHITECT(S) (INCLUDE SOURCE)				
1806 (1869 Sachsey <u>мар</u>) Unknown				
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)				
Original use presumed to be a residence with a ground floor shop based on structural				
arrangement and detailing of storefront. Decorative brick stringer course, interior mouldings and trims are typical of the period.				
STYLE (IF APPROPRIATE)				
Victorian				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)				
Brick bearing walls; wood joists and floors; built-up roof; wood doors, windows stone sill				
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)				
Overall 18' x 58'	Front 18' x 30	Rear 12	2 × 28 · (see sketch plan)
EXTERIOR FEATURES OF NOTE				
Decorative string courses; red brick common bond, corbeled brick cornice, flat-arched window openings with decorative brickwork surrounds				
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NDT SKETCHED) Metal ceiling in 1st floor front room. Bullseye window and door trim, board and bead wainscoting in stairs and utility rooms, wood floors.				
MAJOR ALTERATIONS AND ADDITIONS WITH DATES				
Storefront alterations, date unknown.				
PRESENT CONDITION AND USE				
Vacant - rear of building suffering substantial damage from brick robbers.				
OTHER INFORMATION AS APPROPRIATE				
For photographs, see HABS No. MD-904. Building is to be renovated for cooperative housing for artists.				
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)				
1869 Sachsey Map, 1887 Bromley Map, Sanborn Maps 1902, 1911, 1927, 1932				
COMPILER, AFFILIATION				DATE
Peter C. Doo AIA Walter Sc	hamu & Associa	ates		23 Sept, 1985_

